



**REQUEST FOR QUOTATION**

<b>Vendor Name</b>	J.M.Solutions FZE	<b>PR Type</b>	Spare	<b>Priority</b>	Within 1 month
<b>PR Number</b>	SPR/MNSR/E/24/087	<b>Vessel</b>	MNSR - UACC MANSOURIA	<b>Supply Date</b>	07/20/2024
<b>Ship Builder</b>	SHINA Sb YARD CO. Ltd., Tongyeong, KOREA	<b>Hull No</b>	S 546	<b>Supply Port</b>	BINTULU - MALAYSIA
<b>PR Description</b>	LIGHTING FIXTURE SPARE PARTSMIRROR LIGHTING				

**MACHINERY DETAILS**

<b>Machine Name</b>	Engine Room Lights-LIG4	<b>Model</b>	f1240ws-0206giuwnm2h	<b>Address</b>	
<b>Maker</b>	daeyang elec co ltd	<b>Year Of Mfg.</b>			
		<b>Serial No</b>			

SNo	Item Description	Component No./ Part No.	Drawing No.	Item No	Req Qty.	Uom	Remarks
1	LAMP HOLDER		L11480186	3,4	200	PIECES	LAMP HOLDER POLYCARBONATEIN PAIR(REFER PICTURE)DUE TO AGING AND HEAT LAMP HOLDER OF APPROXIMATELY 75% LIGHT FITTINGS HAVE GONE BRITTLE AND FALLING OFF WHILE REPLACING TUBE LIGHTS
2	FLUORESCENT MIRROR LIGHT		L16630030	1-15	10	PIECES	MIRROR LIGHTS AS PER DIMENTIONS MENTIONED IN DOCUMENT ATTACHEDL=534MM B= 70 MM220 V, 60HZBROKEN AND FITTINGS WITH COMPROMISED WATER TIGHT INTEGRITY NEED TO BE REPLACED
3	HALOGEN LAMP HOLDER		L46580003	11	10	PIECES	REQUIRED REPLACEMENT FOR COMPLETELY DAMAGED HIGH TEMPRATURE APPLICATION CERAMIC HOLDERS