



## REQUEST FOR QUOTATION

Vendor Name	YIHAI MARINE-HK CO LIMITED	PR Type	Spare	Priority	Within 1 month
PR Number	SPR/MSLA/D/24/081	Vessel	MSLA - UOG STENIES	Supply Date	12/07/2024
Ship Builder	SHINAsb Yard Co. Ltd., Tongyeong, Korea	Hull No	S 545	Supply Port	OTHER - OTHER
PR Description	FRAMO SYSTEM ELECTRICAL SPARES				

## MACHINERY DETAILS

Machine Name	Framo	Model	O.NOS.: 615781-788	Address
Maker	FRANK MOHN SERVICES AS	Year Of Mfg. Serial No		

SNo	Item Description	Component No./ Part No.	Drawing No.	Item No	Req Qty.	Uom	Remarks
1	SUPPLY POWER, RECTIFIER UNIT A41481	STK/A38382	0381-4647-2	137	3	PIECES	SUPPLY POWER,RECTIFIER UNIT A41481 ,ARTICLE NO:A38382, G01,G02,G21 THESE POWER UNITS IS ALREADY BYPESSED . FOR THE SAFETY OF FRAMO CONSOLE AND PLC SYSTEM VESSEL NEED THESE RECTIFIER UNIT. ONBOARD NOT HAVE SPARE.
2	PLC MAIN UNIT D01	STK/A69240	0381-4647-2	161	1	PIECES	PLC MAIN UNIT D01. FRAMO SYSTEM PLC UNIT D01 IS MALFUNCTIONING PLC FAILURE ALARM COME ON THE PANEL VESSEL HAVE NOT SPARE PLC.