



**REQUEST FOR QUOTATION**

<b>Vendor Name</b>	The Work Shop Pte. Ltd	<b>PR Type</b>	Spare	<b>Priority</b>	Within 1 week
<b>PR Number</b>	SPR/INSV/E/24/071	<b>Vessel</b>	INSV - UOG IOANNIS V	<b>Supply Date</b>	06/07/2024
<b>Ship Builder</b>	New Times Shipbuilding Co Ltd	<b>Hull No</b>	(0307348)	<b>Supply Port</b>	AMSTERDAM - NETHERLANDS
<b>PR Description</b>	WATER-BLASTER CE20- 500 - REPAIR KIT				

**MACHINERY DETAILS**

<b>Machine Name</b>	Hydroblaster	<b>Model</b>	CE20-500	<b>Address</b>	
<b>Maker</b>	DEN JET	<b>Year Of Mfg.</b>			
		<b>Serial No</b>			

SNo	Item Description	Component No./ Part No.	Drawing No.	Item No	Req Qty.	Uom	Remarks
1	REP. KIT FOR GUN 560BAR	Pos.21,24,25, 26,27,30,31		8140086 1	2	KIT	VESSEL DONT HAVE SPARE FOR OVERHAULING THE GUN.NOW INSIDE GUN PISTON BROCKENED.
2	SUCTION VALVE KIT	47		8120061 2	1	KIT	OIL LEAKAGE FROM SUCTION VV - NEED TO REPAIR
3	BACK UP RING REP. KIT	79		8120063 4	1	KIT	
4	SEAL REP.KIT	60		8120061 9	1	KIT	OIL LEAKAGE FROM PUMP BODY - NEED TO REPAIR
5	REP KIT FOR UNLOADER AND SAFETY VALVE	81300619		8130061 9	2	KIT	NO SPARE ONBOARD. - NEEDED SPARES ONBOARD AS PER MANUAL
6	O-RING	80		8020061 2	6	PIECES	
7	OIL SEAL	81		8120063 5	3	PIECES	
8	OIL SEAL	33		8120060 3	6	PIECES	
9	GUIDE BEARING	32		8120090 3	6	PIECES	
10	OUTLET FITTING	27		8130028 9	2	PIECES	OUTLET FITTINGB GOT BROKENED .